## Maryland Historical Trust Maryland Inventory of Historic Properties number: AL-I-AOSI Name: 5 Me CREEK & OVER 15 Me CREEK.

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.				
MARYLAND HISTORIC Eligibility Recommended  Criteria:AB \( \subseteq \text{C} \)D Considerations:  Comments:	Eligibility Not RecommendedX			
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001 Date:3 April 2001			

Jus

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

MHT Number AL-I-A-081

Name and SHA No. Fifteen Mile Creek Road over Fifteen Mile Creek/A11000 (A11010)
<u>Location:</u> Street/Road Name and Number: <u>Fifteen Mile Creek Road</u>
City/Town: Pratt Vicinity x
County: Allegany
Ownership:State_x_County_Municipal_Other
This bridge projects over: _Road_Railwayx Water_Land
Is the bridge located within a designated district: _yes_x_no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
_Timber Bridge _Beam Bridge_Truss-Covered_Trestle _Timber-and-Concrete
_Stone Arch
_Metal Truss
_Movable Bridge _Swing _Bascule Single Leaf_Bascule Multiple Leaf _Vertical Lift _Retractile_Pontoon
<u>x</u> Metal Girder <u>x</u> Rolled Girder _ Rolled Girder Concrete Encased  _ Plate Girder _ Plate Girder Concrete Encased

_Metal Suspension
_Metal Arch
_Metal Cantilever
_Concrete _Concrete Arch _Concrete Slab_Concrete Beam _Rigid Frame _Other Type Name
Description:
<b>Describe Setting:</b> A11000 (A11010) carries Fifteen Mile Allegany County, Maryland. Fifteen Mile Creek Road of Mile Creek flows generally east-west. The bridge is lestructures in view. Fifteen Mile Creek has a wooded characteristic.

Allegany County, Maryland. Fifteen Mile Creek Road runs north-south at this location; Fifteen Mile Creek flows generally east-west. The bridge is located in a wooded rural area with no structures in view. Fifteen Mile Creek has a wooded channel bank at this location. The bridge is located within Green Ridge Forest.

**Describe Superstructure and Substructure:** The superstructure is a single span steel beam bridge with a timber deck and timber curb. There are W-beam guardrails and channel posts mounted to the exterior beams. The length of the span 31' with a total bridge length of 34'. In the 1993 inspection report it was recommended that the deck be replaced as soon as possible. The steel beams show some rust damage, but nothing severe. The substructure is two concrete abutments and wing walls. The abutments and wing walls are slightly undermined and beginning to show some scour. The 1993 inspection report recommends cleaning and monitoring the channel flow to prevent further undermining.

**Discuss Major Alterations:** The structure was rebuilt in 1964. This entailed replacement of the beams, deck and abutments. In 1987 a new timber deck was installed.

## **History:**

When Built:1940

Why Built: local transportation needs

Who Built:

Why Altered: structural and safety improvements

Was this bridge built as part of an organized bridge building campaign: yes

## **Surveyor Analysis:**

This bridge may have	NR significance	for association	with
_A Events	_Person		

\_C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:no

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area:no

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district:no

Is the bridge a significant example of its type:no

Does the bridge retain integrity of the important elements described in the Context Addendum: A11000 (A11010) was entirely rebuilt in 1964. This reconstruction included replacement of the steel beams and abutments (primary CDE's) and the deck and floor system (secondary CDE's). The deck was again replaced in 1987. These modifications have caused A11000 (A11010) to lose its integrity.

Should this bridge be given further study before significance analysis is made and why:Because of the extensive repairs made to the bridge, further study is not necessary.

## **Bibliography:**

Allegany County

v.d. Bridge Inspection Files

Greiner, Inc.

1995 Historic Bridge Inventory Form

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context

United States Geological Survey

1950, 7.5' Artemas Quadrangle, photorevised 1974

Allegany County Bridge Files


Spero, P.A.C. & Company, and Louis Berger & Associates Historic Bridges in Maryland: Historic Bridge Context, September 1994.

Surveyor:

Name: Stephanie L. Bandy Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213

Address: 2323 West Joppa Road Brooklandville, MD 21022





BR # 20/10/0 (4/100) AL-I-A-081 OVER FIFTEEN MILE (RLEC ALLEGANY CO. MD DAVID KING 2/3/95 5.4.4. WEST ELEVATION (DOWNSTREAM) 1 OF 4



ALLEGANY CO., MD

DAYID KING

2/3/95

S. H. A

NORTH APPROACH

2 07 4



ALJ-A-081 BR# 20AMOID (AMOOD)

OVER FIFTEEN MILE CREEK

ALLEGANY CO., MD

DAYID KING

2/3/95

S. H. A.

SOUTH ATPROACH

3 0 = 4



AL-I-A-081 BR # 20A11010 (A 11000) OVER FIFTEEN MILE CREEK ALLEGANY CO IND DAVID KING 2/3/95 EAST ELEVATION (UTSTREAM)

4 OF 4